



# YOUR LABORATORY LOGO

3350 Monte Villa Parkway Bothell, WA 98021

## WORK ORDER

**P806001**

Printed: 07/09/2019 11:11 am

**Project:** Agate Remediation-Weekly  
**Project Number:**  
**Project Manager:** Mike Arnold

**Report To:**

Compliance Testing  
 Mary Stead  
 6281 Pleasant Blossom St  
 Caraquet, NE 68842  
 Phone: (402) 339-6717  
 Fax: (402) 339-6700

**Invoice To:**

Compliance Testing  
 Amy Lou  
 6281 Pleasant Blossom St  
 Caraquet, NE 68842  
 Phone: (402) 339-6717  
 Fax: (402) 339-6700

Date Logged In: 06/01/2018 03:10 PM  
 Date Received: 06/01/2018 12:00 AM  
 Date Due: 06/15/2018 (10 day TAT)

Logged In By: Dee Beaye  
 Received By: Dee Beaye

Cooler Data	
Samples Received at:	Received On Ice <span style="float: right;">No</span>
Containers Properly Preserved	No
COC/Labels Agree	No
Preservation Confirmed	No

Analysis	Due	TAT	Expires	Comments
----------	-----	-----	---------	----------

**P806001-01 North End [Water] Sampled 7/8/2018 12:00:00AM**

*Sample Comments: Process*

Mn (Manganese) - 200.7 - Total	06/15/2018 00:00	10	01/04/2019 00:00	
Chloride by IC (300.0/9056A)	06/15/2018 00:00	10	08/05/2018 00:00	
Coliform, Total (P/A)	06/15/2018 00:00	10	07/09/2018 00:00	
Fe (Iron) - 200.7 - Total	06/15/2018 00:00	10	01/04/2019 00:00	
Flow	06/15/2018 00:00	10	07/08/2018 03:36	
Sulfate by IC (300.0/9056A)	06/15/2018 00:00	10	08/05/2018 00:00	
Solids, Total Suspended (TSS)	06/15/2018 00:00	10	07/15/2018 00:00	
Nitrate by IC (300.0/9056A)	06/15/2018 00:00	10	08/05/2018 00:00	
Al (Aluminum) - 200.7 - Total	06/15/2018 00:00	10	01/04/2019 00:00	

***Samples subcontracted to: Beaker Laboratory***

**P806001-01 North End [Water] Sampled 7/8/2018 12:00:00AM**

*Sample Comments: Process*

VOC 8260 BTEX	06/15/2018 00:00	10	07/22/2018 00:00	
---------------	------------------	----	------------------	--